

# Inspection Photos

Loc: 381617

Operator: FOUR CORNERS ENERGY LLC

Inspection Date: 4/19/2023



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc:381617 | Date: 4/19/2023

## Inspection Photos



**Photo 1.** Facing west at the location. The vegetation has not re-established in this area approx. 1560'x150'.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc:381617 | Date: 4/19/2023

## Inspection Photos



**Photo 2.** Facing northeast at the location. The vegetation has not re-established in this area approx. 1560'x150'.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc:381617 | Date: 4/19/2023

## Inspection Photos



**Photo 3.** Facing northwest at the well site. There is some remnant gravel that remains in this area and there is no vegetation growth approx. 70'x70'.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc:381617 | Date: 4/19/2023

## Inspection Photos



**Photo 4.** Facing southeast at the well site. There is some remnant gravel that remains in this area and there is no vegetation growth approx. 70'x70'.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc:381617 | Date: 4/19/2023

## Inspection Photos



**Photo 5.** Facing northwest toward the surrounding pinyon/juniper/sage shrubland



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc:381617 | Date: 4/19/2023