

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad

Location ID: 335263



Photo # 6265 From entrance to location



Photo # 6266 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad

Location ID: 335263




Photo # 6268 Debris



Photo # 6276 Erosion on edge of spur road near ditch

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad

Location ID: 335263



Apr 25, 2023 at 10:15:50 AM
CO

Photo # 6277 Check dam needs maintenance (in ditch along spur road)



Apr 25, 2023 at 10:16:08 AM
CO

Photo # 6278 Check dam needs maintenance (in ditch along spur road)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad

Location ID: 335263



Photo # 6279 Ditch & rip rap need maintenance (along spur road)



Photo # 6280 Ditch & rip rap need maintenance (along spur road)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad

Location ID: 335263



Photo # 6281 Erosion on spur road



Photo # 6282 Erosion & transport of sediment off spur road & into vegetation

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad

Location ID: 335263



Photo # 6285 Erosion & transport of sediment off spur road into vegetation/insufficient BMP's



Photo # 6286 Erosion & transport of sediment off spur road into vegetation/insufficient BMP's

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad

Location ID: 335263



Photo # 6287 Transport of sediment off spur road into vegetation/insufficient BMP's



Photo # 6290 Erosion along edge of spur road

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad

Location ID: 335263



Photo # 6297 Erosion & transport of sediment off spur road into vegetation



Photo # 6292 Erosion & transport of sediment off spur road into vegetation

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad

Location ID: 335263



Photo # 6293 Erosion & transport of sediment off spur road into vegetation



Photo # 6294 Erosion & transport of sediment off spur road into vegetation/insufficient BMP's

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad

Location ID: 335263



Photo # 6295 Erosion & transport of sediment off spur road into vegetation



Photo # 6296 Erosion & transport of sediment off spur road into vegetation/insufficient BMP's

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 200-20 Pad

Location ID: 335263



Photo # 6298 Erosion & transport of sediment off spur road into vegetation/insufficient BMP's



Photo # 6299 Erosion & transport of sediment off spur road into vegetation/insufficient BMP's