

Inspection Photos
Seeley Spargo 1-36
API 033-06091



Photo #1. Overview of well location.



Photo #2. View of wellhead and flowline assembly.

Inspection Photos
Seeley Spargo 1-36
API 033-06091



Photo #3. Horizontal separator (westside #1) eroded containment berm.

Inspection Photos
Seeley Spargo 1-36
API 033-06091



Photo #4. Abandoned flow line in tank battery.