

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/20/2023

Submitted Date:

05/01/2023

Document Number:

709100040**FIELD INSPECTION FORM**Loc ID 317032 Inspector Name: Heibel, Krystal On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments7 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Krystal Heibel	(303) 817-5217	krystal.heibel@state.co.us	
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
234647	WELL	PR	05/14/1956	OW	121-06776	GEBAUER 1	PR
431878	TANK BATTERY	AC	04/14/2009		-	GEBAUER-61N54W 15NWNE	AC

General Comment:

On April 20, 2023, COGCC Environmental Staff Krystal Heibel conducted an environmental field inspection of Fritzler Resources Inc.

The following is a summary:

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) and corrective action due dates from previous inspections that have not been addressed are still applicable.

LocationOverall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:	Sign not posted at tank battery.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	05/26/2023

Emergency Contact Number:			
Comment:	Emergency contact number illegible from a distance.		
Corrective Action:	Comply with Rule 605.e. and g.		Date: 05/26/2023

Good Housekeeping:			
Type	TRASH		
Comment:	Trash observed throughout site.		
Corrective Action:	Comply with Rule 606.		Date: 05/26/2023
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment left onsite (two barrels of oil, sheets of wood).		
Corrective Action:	Comply with 902.b. Any unused equipment needs to be removed and the crude oil in the barrels need to be properly disposed of as E&P waste.		Date: 05/26/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	
Crude Oil	WELLHEAD	<= 1 bbl	
Comment:	Hydrocarbons observed around the wellhead.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date: 05/26/2023
Crude Oil	Treater	<= 1 bbl	
Comment:	Hydrocarbons observed in a 5 gallon paint bucket within the treater shed.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date: 05/26/2023
Crude Oil	Tank	<= 1 bbl	
Comment:	Hydrocarbons observed around several locations around the tank battery.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date: 05/26/2023

In Containment: Yes

Comment: ☒ Multiple Spills and Releases?

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	



Inspected Facilities									
Facility ID:	234647	Type:	WELL	API Number:	121-06776	Status:	PR	Insp. Status:	PR
Facility ID:	431878	Type:	TANK	API Number:	-	Status:	AC	Insp. Status:	AC

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709100041	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6099355