

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 96-28 Pad

Location ID: 335122



Photo # 6627 From entrance to location



Photo # 6628 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 96-28 Pad

Location ID: 335122



Photo # 6629 Location



Photo # 6630 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 96-28 Pad

Location ID: 335122



Photo # 6631 Location



Photo # 6643 Stained soils & gravel

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 96-28 Pad

Location ID: 335122



Photo # 6645 Stained soils & gravel



Photo # 6649 Stained soils & gravel

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 96-28 Pad

Location ID: 335122



**Photo # 3430 From Inspection 708900178 conducted on 03/27/2023 Meter calibration info not conspicuously posted**

**Photo # 6632 Meter calibration info not conspicuously posted**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 96-28 Pad

Location ID: 335122



Photo # 3429 From Inspection 708900178 conducted on 03/27/2023 Meter calibration info not conspicuously posted



Photo # 6633 Meter calibration info not conspicuously posted

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 96-28 Pad

Location ID: 335122



Photo # 6650 Debris

Photo # 6654 Debris

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 96-28 Pad

Location ID: 335122



Photo # 6655 Debris