

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/01/2023

Submitted Date:

05/01/2023

Document Number:

712700081

FIELD INSPECTION FORMLoc ID 333085 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|-------|---------------------------------------|--------------------------|
| , General | | FarmingtonRegulatoryTechs@hilcorp.com | All SW field inspections |
| Labowskie, Steve | | steve.labowskie@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 214340 | WELL | PR | 04/01/2018 | GW | 067-05735 | MCDONALD 1 | PR |
| 216434 | WELL | PR | 01/13/1997 | CBM | 067-08040 | REININGHAUS 1-7 | PR |
| 295406 | WELL | PR | 09/10/2008 | CBM | 067-09527 | REININGHAUS 2-7 | PR |

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

LocationOverall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|----------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: [Present](#)

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|---------------------------|-------|--|
| Type | LOCATION | | |
| Comment: | Barb wire | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | Hog fence | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|---------------------------|--------------------------|-------|-----------------|
| Type: Deadman # & Marked | # 6 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Wellhead | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Flow Line | # 2 | | |

| | | | | |
|-----------------------------------|--|--|-------|--|
| Comment: | 2" from separator to tank 3" from well to separator | | | |
| Corrective Action: | | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Type: Gas Meter Run | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |

Tanks and Berms:

| | | | | | | |
|--------------------|---------------------------------------|----------|----------|---------|-----------------------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 1 | 100 BBLs | Open Top | | 37.027460,-107.546090 | |
| Comment: | Partially buried, open top, screened. | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Wells Served By Facilities Above

| |
|------------|
| API Number |
| 067-09527 |
| 067-08040 |

AirsID

| | |
|------------|--------|
| API Number | AirsID |
|------------|--------|

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Gravel | Pass | | | |

Comment: [No visible erosion or sediment migration observed during inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------|---|
| 712700082 | Wellhead Location Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6099721 |