

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/01/2023

Submitted Date:

05/01/2023

Document Number:

712700083

FIELD INSPECTION FORM

Loc ID 333085 Inspector Name: Pattillo, Curtis On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Findings:

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		FarmingtonRegulatoryTechs@hilcorp.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214340	WELL	PR	04/01/2018	GW	067-05735	MCDONALD 1	PR
216434	WELL	PR	01/13/1997	CBM	067-08040	REININGHAUS 1-7	PR
295406	WELL	PR	09/10/2008	CBM	067-09527	REININGHAUS 2-7	PR

General Comment:

[SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	Barb wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panel and sound abatement walls.		
Corrective Action:		Date:	

Equipment:

Type	Equipment	Quantity	Comment	Corrective Action	Date	corrective date
Type: Deadman # & Marked		# 6				
Comment:						
Corrective Action:					Date:	
Type: Pump Jack		# 1				
Comment:						
Corrective Action:					Date:	
Type: Flow Line		# 2				
Comment:			3" from separator to meter 3" from well to separator			
Corrective Action:					Date:	
Type: Prime Mover		# 1				
Comment:			gas motor			
Corrective Action:					Date:	
Type: Vertical Heated Separator		# 1				
Comment:						
Corrective Action:					Date:	
Type: Bradenhead		# 1				

Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	#		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Wellhead		
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 214340 Type: WELL API Number: 067-05735 Status: PR Insp. Status: PR

Facility ID: 216434 Type: WELL API Number: 067-08040 Status: PR Insp. Status: PR

Facility ID: 295406 Type: WELL API Number: 067-09527 Status: PR Insp. Status: PR

BradenHead

Date of Last Brhd Test: 05/17/2022 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			

Comment: No visible erosion or sediment migration observed during inspection.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700084	Well Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6099722