

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/28/2023

Submitted Date:

05/02/2023

Document Number:

699805565

**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 312697      De Paolo, Corey      2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER      State: CO      Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

15      Number of Comments

1      Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273858	WELL	SI	03/01/2022	GW	077-08824	HYRUP 12-74	SI

**General Comment:****COGCC Inspection Report Summary**

On 4/27/23 at approximately 14:00 hours, I, Inspector Corey De Paolo,  
 Conducted an on-site inspection at CAERUS PICEANCE LLC SGV /12H PAD.  
 Location #312696 Mesa County Colorado  
 While there, I observed normal production operations.  
 During this inspection the following compliance issues were observed:

1) -Insufficient Stock piled soils BMPs.

-Access road lacks stabilization.

-Gravel insufficient

-Insufficient tracking BMP at entrance to Access road. To minimize the transport of sediment with a CA date of 5/17/23.

-Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the  
 Compliance issues have been corrected to comply with COGCC rules.  
 This is a summary of the inspection report

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

**Equipment:**

Type: Bird Protectors	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	OTHER	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	210 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	273858	Type:	WELL	API Number:	077-08824	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder:									
Comment: Last produced Februray 2023									
Corrective Action: Date:									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
		Ditches				
Other	Fail					-Insufficient Stock piled soils BMPs.
		Other	Fail			Insufficient tracking BMP at entrance to Access
		Culverts				
Gravel						
Ditches						
		Gravel	Fail			-Gravel insufficient
Berms						
		Compaction	Fail			-Access road lacks stabilization.

Comment: -Insufficient Stock piled soils BMPs.  
 -Access road lacks stabilization.  
 -Gravel insufficient  
 -Insufficient tracking BMP at entrance to Access road. To minimize the transport of sediment.

Corrective Action: -Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations in a manner that minimizes erosion, transport of sediment off site and site degradation.

Date: 05/17/2023

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Refer to Storm water for corrective actions	depaoloc	05/02/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699805566	Storm water photo log Insp. #699805565	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6101540">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6101540</a>