

**Scout Energy Management LLC
Union Pacific 16-27
Location #314609**




Access road to location



Entrance to location

**Scout Energy Management LLC
Union Pacific 16-27
Location #314609**



Wellhead and well sign



Erosion and sediment migration to location

**Scout Energy Management LLC
Union Pacific 16-27
Location #314609**



BMP lack of maintenance



Sediment migration from diversion ditch

**Scout Energy Management LLC
Union Pacific 16-27
Location #314609**



Erosion and sediment migration



Erosion and sediment migration

**Scout Energy Management LLC
Union Pacific 16-27
Location #314609**



West side of location sediment migration



Vehicle tracking BMPs need implemetation

**Scout Energy Management LLC
Union Pacific 16-27
Location #314609**



Location view from Southeast corner



Location view from Southwest corner

**Scout Energy Management LLC
Union Pacific 16-27
Location #314609**



Location view from Northwest corner



Location view from Northeast corner