

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate. Sign is beginning to fade and peel, will need to be replaced in the near future.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused pump jack disassembled on location		
Corrective Action:	Comply with Rule 606 unused equipment	Date:	10/27/2021
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	unused pump jack has hog fence around it		
Corrective Action:		Date:	
Equipment:			
Type: Plunger Lift	# 1	corrective date	
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	disassembled and unused		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	automation		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	appears plumbed to surface		
Corrective Action:		Date:	
Venting:			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--	--	--

Inspected Facilities

Facility ID: 245782 Type: WELL API Number: 123-13577 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 01/25/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 4/26/2023 at approximately 1200 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Follow up inspection to Doc # 699304327 & 702400101. Operator: KP Kauffman Location: George H. Gerhardt #4 API #05-123-13577 County: Weld. While there, I observed a wellsite, SI at the time of inspection. During this inspection the following possible compliance issue was observed and is delinquent: 606 housekeeping: Unused pumpjack disassembled on location, CA date 10-27-2021. The following compliance issue has been addressed: 606 housekeeping: Weeds overgrown throughout location have been cut. See attached photos. Location: muddy. Weather: cloudy. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	04/26/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403385860	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6094766
702401895	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6094756