

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/24/2023

Submitted Date:

04/26/2023

Document Number:

708900353

FIELD INSPECTION FORMLoc ID 335136 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

19 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Byers, Jim		jbyers@blm.gov	
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211215	WELL	PR	12/19/1995	GW	045-06974	FEDERAL RMV-33-20	PR
265048	WELL	PR	01/07/2004	OW	045-08978	FEDERAL RWF 334-17	PR
265049	WELL	PR	09/23/2002	OW	045-08979	FEDERAL RWF 344-17	PR
279142	WELL	PR	08/03/2005	GW	045-11004	GARFIELD COUNTY RWF 541-20	PR
279146	WELL	PR	08/03/2005	GW	045-11008	GARFIELD COUNTY RWF 441-20	PR

General Comment:**COGCC Inspection Report Summary**

On 04/24/2023 at approximately 12:35 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC RMV 33-20 pad. Location # 335136 in Garfield County Colorado. Location is within High Priority/Density Habitat areas. While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Stained soils & gravel on location with a CA date of 05/06/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Remote location/split pad - Wellheads only, production equipment for this pad is located on the CLOUGH 135, location # 322438 Please refer to Inspection 708900354 for location associated with this one.

This location is inside the Garfield County Landfill.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Wellhead signs are weathered & cracking but still legible		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911/970-285-9377	Date:	
Corrective Action:		Date:	

Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris - Please refer to photo log		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Stained soils & gravel on location		
Corrective Action:	Remove and properly dispose of all stained soils and gravel.	Date:	05/06/2023

Overall Good: ☐

Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 5		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:	Marked		
Corrective Action:		Date:	
Type: Bradenhead	# 5		

Comment:	RMV 33-20 & RWF 334-17 wells have Taylor plugs on bradenhead, bradenhead valves accessible. No form of pressure monitoring equipment located on the other 3 wells bradenheads. All bradenhead valves are accessible.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	211215	Type:	WELL	API Number:	045-06974	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	265048	Type:	WELL	API Number:	045-08978	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	265049	Type:	WELL	API Number:	045-08979	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	279142	Type:	WELL	API Number:	045-11004	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	279146	Type:	WELL	API Number:	045-11008	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						Sparse
		Compaction				
		Ditches				
		Culverts				
Compaction						Light in some areas
		Gravel				Sparse

Comment: Location appears to have some gravel throughout the location with light compaction. Places with sparse to no gravel are present on location. Sparse gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to Housekeeping for observed compliance issue.	smelserw	04/26/2023
Remote location/split pad - Wellheads only, production equipment for this pad is located on the CLOUGH 135, location # 322438 Please refer to Inspection 708900354 for location associated with this one.		
This location is inside the Garfield County Landfill.		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403385869	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6094774
708900355	Inspection 708900353 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6094765