

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/02/2023

Submitted Date:

05/03/2023

Document Number:

712700091

FIELD INSPECTION FORMLoc ID 438700 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10464

Name of Operator: CATAMOUNT ENERGY PARTNERS LLC

Address: 1001 17TH STREET STE 1160

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Costa, Ryan		ryan.costa@state.co.us	
, General		Inspections@catamountep.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438701	WELL	PR	06/06/2015	CBM	067-09914	Carpenter 32-6-3 2	PR
440523	WELL	PR	06/16/2015	CBM	067-09918	Carpenter 32-6-3 1S	PR

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

LocationOverall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: [Present](#)

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Meterhouse, cattle panel		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Telemetry, cattle panel		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog fence		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Cattle panel		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Cattle panel		
Corrective Action:		Date:	

Equipment:

Type: Horizontal Heated Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		

Comment: Wellheads		Date:	
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:		Date:	
Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:		Date:	
Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment: 3" from wellhead to separator.		Date:	
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:		Date:	
Corrective Action:		Date:	
Type: Vertical Heated Separator	#		
Comment:		Date:	
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment: Telemetry		Date:	
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:		Date:	
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment: gas motor		Date:	
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:		Date:	
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	STEEL AST		37.045460,-107.484970
Comment:		Date:			
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Inspector Name: Pattillo, Curtis

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment: Plastic liner visible under gravel.					
Corrective Action:				Date:	

Wells Served By Facilities Above

AirsID

API Number
067-09918

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	438701	Type:	WELL	API Number:	067-09914	Status:	PR	Insp. Status:	PR
Facility ID:	440523	Type:	WELL	API Number:	067-09918	Status:	PR	Insp. Status:	PR
BradenHead									
Date of Last Brhd Test:		12/30/2021		Annual Brhd Completed?					
Last Brhd Test Results		Initial Surf Csg Pressure:		2		Fluid Type:		NONE	
		End Surf Csg Pressure:		0					
Comment:		<div></div>							
Corrective Action:		<div></div>						Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	
Waddles	Fail	Culverts	Pass			

Comment: [Installed wattles along eastern side of location berms must be maintained or removed. Previous inspection on 1/11/2022 required the installation of BMPs and spot seeding. The area has not been stabilized, reseeding as not been successful. Contact the SW Reclamation Specialist Ryan Costa regarding interim reclamation. See Photos #2 & #3.](#)

Corrective Action: [Comply with Rule 1002.f. & Rule 1003.](#)

Date: 05/05/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700096	Well Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6102653