

## Inspection Photos

Location Name: CAERUS PICEANCE LLC M. DUTTON-68S95W /7SWSW.

Location ID: 334127



Photo #9792 From entrance to location.



Photo #9793 From entrance to location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC M. DUTTON-68S95W /7SWSW.

Location ID: 334127



**Photo #9809 Multiple flowline heating insulation open ended.**



**Photo #9815 Unused equipment.**