

Stormwater Management and Erosion control
Location Name: CAERUS PICEANCE LLC M. DUTTON-68S95W /7SWSW
Location #: 334127



Northwest corner of location.



Northeast corner of location.



Southwest corner of location.



Southeast corner of location.

Stormwater Management and Erosion control
Location Name: CAERUS PICEANCE LLC M. DUTTON-68S95W /7SWSW
Location #: 334127



Photo #9800 Location lacks stabilization.



Photo #9801 Location lacks stabilization.

Stormwater Management and Erosion control
Location Name: CAERUS PICEANCE LLC M. DUTTON-68S95W /7SWSW
Location #: 334127



Photo #9802 Location lacks stabilization.



Photo #9811 Insufficient track BMP at entrance to location to minimize the transport of sediment.

Stormwater Management and Erosion control
Location Name: CAERUS PICEANCE LLC M. DUTTON-68S95W /7SWSW
Location #: 334127



Photo #9814 Insufficient track BMP at entrance to location to minimize the transport of sediment.



Photo #9796 Expanded use of the location.

Stormwater Management and Erosion control
Location Name: CAERUS PICEANCE LLC M. DUTTON-68S95W /7SWSW
Location #: 334127



Photo #9806 sediment choking off vegetation



Photo #9807 sediment choking off vegetation

Stormwater Management and Erosion control
Location Name: CAERUS PICEANCE LLC M. DUTTON-68S95W /7SWSW
Location #: 334127



Photo #9812 Insufficient stockpiled soils BMP's.



Photo #9813 Insufficient stockpiled soils BMP's.