

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/01/2023

Submitted Date:

05/03/2023

Document Number:

705000289

**FIELD INSPECTION FORM**Loc ID 319811 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10459

Name of Operator: EXTRACTION OIL &amp; GAS INC

Address: 370 17TH STREET SUITE 5200

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201446	WELL	SI	08/01/2018	GW	001-06849	MERKOWITZ 1	TA
452750	LOCATION	AC			-	Merkowitz #1 Tank Battery	EG
465168	OFF-LOCATION FLOWLINE	AC			-	Merkowitz #1 Tank Battery	EG

**General Comment:**COGCC Engineering Integrity Inspection; Flowline Inspection  
Photos uploaded

**Inspected Facilities**

Facility ID: <u>201446</u>	Type: <u>WELL</u>	API Number: <u>001-06849</u>	Status: <u>SI</u>	Insp. Status: <u>TA</u>
Facility ID: <u>452750</u>	Type: <u>LOCATION</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EG</u>
Facility ID: <u>465168</u>	Type: <u>OFF-</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EG</u>

**Flowline**

#1	Type: Non-Well Site	1 of Lines
----	---------------------	------------

Flowline Description

Flowline Type: Non-Well Site      Size: 3"      Material: Fiberglass  
Variance:      Age:      Contents:

Integrity Summary

Failures:      Spills:      Repairs Made:  
Coatings:      H2S:      Cathodic Protection:

Pressure Testing

Witnessed:      Test Result:      Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation    ☐ 1102. Operations, Maintenance, and Repair    ☒ 1103. Abandonment

Comment: Well (Merkowitz 1-34-1-66) is Temporarily Abandoned; fenced excavations observed at TA WH and facility/ battery areas. The off location WH flowline removal/ AIP appears to be in progress. The OLF has been partially removed; segments removed at the wellhead and facility/ battery. (1) 3" fiberglass OLF was observed in excavations at WH and facility; the remaining section (approx 600') runs NE from the wellhead and is pinflagged through an existing crop circle. The facility/ tank battery is decommissioned; tanks and equipment removed. Excavation/ form 27 work is in progress.

Corrective Action:      Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000294	TA well and signage; FL excavation	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6103257">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6103257</a>
705000295	OLF excavation at facility/ battery; view SW to well	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6103258">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6103258</a>
705000296	View of location; flowline pipe removed	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6103259">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6103259</a>