

Scout Energy Management LLC
U P 3-34
Location #314375



Entrance off Highway 64



South access road to location

Scout Energy Management LLC
U P 3-34
Location #314375



Well sign lacking public road used to access the well information

North access road to location

Scout Energy Management LLC
U P 3-34
Location #314375



Erosion and sediment migration



Sediment migration from slope

Scout Energy Management LLC
U P 3-34
Location #314375



North side of location diversion ditch berm

West side of location

Scout Energy Management LLC
U P 3-34
Location #314375



Location view from Southwest corner



Location view from Southeast corner

Scout Energy Management LLC
U P 3-34
Location #314375



Location view from Northeast corner

Location view from Northwest corner