

**Scout Energy Management LLC
Union Pacific 17-27
Location #314616**



Access road to location



Entrance to location view

Scout Energy Management LLC Union Pacific 17-27 Location #314616



Well sign lacking public road used to access location information

Slope erosion and sediment migration

**Scout Energy Management LLC
Union Pacific 17-27
Location #314616**



Sediment migrating off slope

Sediment migration off slope

**Scout Energy Management LLC
Union Pacific 17-27
Location #314616**



Location view from Southeast corner



Location view from Northeast corner

**Scout Energy Management LLC
Union Pacific 17-27
Location #314616**



Location view from Northwest corner



Location view from Southwest corner