

**Scout Energy Management LLC  
A.C. McLaughlin 73X  
Location #315337**




**Access road to location**



**Entrance to location from access road**



Scout Energy Management LLC  
A.C. McLaughlin 73X  
Location #315337



Wellhead view and sign



Lack of stabilization. No vehicle tracking pads





**Scout Energy Management LLC  
A.C. McLaughlin 73X  
Location #315337**



**Lack of stabilization. No vehicle tracking pads**



**Lack of stabilization. Vehicle tracking**



**Scout Energy Management LLC  
A.C. McLaughlin 73X  
Location #315337**



**Sediment movement and migration**



**Unstable slope sediment migration**



**Scout Energy Management LLC  
A.C. McLaughlin 73X  
Location #315337**



**Sediment movement and migration**



**Diversion ditch to location**



**Scout Energy Management LLC  
A.C. McLaughlin 73X  
Location #315337**



**Location view from Northwest corner**



**Location view from Northeast corner**



**Scout Energy Management LLC  
A.C. McLaughlin 73X  
Location #315337**



**Location view from Southeast corner**



**Location view from Southwest corner**