

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 31-23H Pad

Location ID: 323919



Photo # 6792 From entrance to location



Photo # 6793 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 31-23H Pad

Location ID: 323919



Photo # 6794 Location



Photo # 6795 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 31-23H Pad

Location ID: 323919



Photo # 6796 Location



Photo # 6825 Containment needs maintenance

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 31-23H Pad

Location ID: 323919



Photo # 3120 From Inspection 708900164 conducted on 03/24/2023 Containment needs maintenance

Photo # 6800 Containment needs maintenance

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 31-23H Pad

Location ID: 323919



Photo # 3119 From Inspection 708900164 conducted on 03/24/2023 Containment needs maintenance

Photo # 6801 Containment needs maintenance

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 31-23H Pad

Location ID: 323919



Photo # 3124 From Inspection 708900164 conducted on 03/24/2023 Meter calibration info not conspicuously posted



Photo # 6805 Meter calibration info not conspicuously posted