

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/03/2023

Submitted Date:

05/03/2023

Document Number:

708900394

**FIELD INSPECTION FORM**

Loc ID 335101 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 14 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262386	WELL	PR	10/13/2002	GW	045-08020	CLOUGH RMW 242-21	PR
277524	WELL	PR	04/02/2006	GW	045-10722	CLOUGH RWF 444-21	PR
277525	WELL	PR	03/22/2006	GW	045-10721	CLOUGH RWF 443-21	PR
277526	WELL	PR	03/27/2006	GW	045-10720	CLOUGH RWF 433-21	PR
277528	WELL	PR	04/03/2006	GW	045-10719	CLOUGH RMV 221-21	PR
286744	WELL	PR	09/14/2006	GW	045-12759	CLOUGH RWF 544-21	PR

**General Comment:**

[COGCC Inspection Report Summary](#)  
On 05/03/2023 at approximately 12:30 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC RMV 242-21 pad. Location # 335101 in Garfield County Colorado.  
Please refer to Inspection 708900288 conducted on 04/13/2023  
Previous corrective action has not been completed & CA date remains 04/26/2023  
Location is within High Priority/Density Habitat areas.  
While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Housekeeping - Stained soils & gravel on location with a CA date of 04/26/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Split pad - Wellheads only, all production equipment associated with these 6 wells is located on the CLOUGH 113 pad, location # 311536

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soils and gravel on location.		
Corrective Action:	Remove and properly dispose of all stained soils and gravel.		Date: 04/26/2023
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bradenhead	# 6		corrective date
Comment:	Taylor plugs located on all bradenhead, all bradenhead valves are accessible.		
Corrective Action:			Date:
Type: Plunger Lift	# 6		
Comment:	All wells on plunger lift		
Corrective Action:			Date:
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	262386	Type:	WELL	API Number:	045-08020	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				
Facility ID:	277524	Type:	WELL	API Number:	045-10722	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				
Facility ID:	277525	Type:	WELL	API Number:	045-10721	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				
Facility ID:	277526	Type:	WELL	API Number:	045-10720	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				
Facility ID:	277528	Type:	WELL	API Number:	045-10719	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				
Facility ID:	286744	Type:	WELL	API Number:	045-12759	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:					Date:				

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Ditches		Ditches				
Berms						
		Culverts				
Compaction						
		Gravel				Sparse
Gravel						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Please refer to Housekeeping for observed compliance issue.	smelserw	05/03/2023
Split pad - Wellheads only, all production equipment associated with these 6 wells is located on the CLOUGH 113 pad, location # 311536		

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708900395	Inspection 708900394 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6103641">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6103641</a>