

VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location # 324270



Location Entrance – Photo #02749



Tank Berm Permeability Insufficient due to Weed Growth – Photo #02750

VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location # 324270



Separator/Weeds – Photo #02755



Rill Erosion Transporting Sediment from Location – Photo #02752

VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location # 324270



Sediment Transport from Access Road to Drainage Ditch – Photo #02762



Sediment Transport from Access Road to Drainage Ditch – Photo #02759

VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location # 324270



Sediment Transport from Access Road to Drainage Ditch – Photo #02760



Rill Erosion on Access Road/Lack of Stabilization – Photo #02765

VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location # 324270



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #02766



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #02767