

**Inspection Photos**  
**Location Name: Stubbs 1**  
**API: 05-061-05055**



**1. Pumping unit and tank battery**



**2. Stained soil next to wellhead and unit**

**Inspection Photos**  
**Location Name: Stubbs 1**  
**API: 05-061-05055**



**3. Stained soil on west side of wellhead**



**4. This is stained soil next to power pole and straight north of tanks**



**Inspection Photos**  
**Location Name: Stubbs 1**  
**API: 05-061-05055**



**5. The west power pole has this stained soil on the east side of it**



**6. This bare spot is west of the Stubbs oil tanks running downhill. There's no vegetation and the landowner has been complaining about bare spots all over his pasture. (Noted by Mr. Kosola on 8/23/22 Insp #700600410 CA date of 9/9/22. And noted on follow-up inspection #700600414 on 8/30/22)**

**Inspection Photos**  
**Location Name: Stubbs 1**  
**API: 05-061-05055**



**7. Here is some more stained soil that the landowner has also complained about to the north of the Stubbs wellhead along an old access trail**

