

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/02/2023

Submitted Date:

05/04/2023

Document Number:

708900396

FIELD INSPECTION FORM

Loc ID 324053 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
12 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: 1058 COUNTY ROAD 215
 City: PARACHUTE State: CO Zip: 81635

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211586	WELL	PR	08/02/2001	GW	045-07347	CLOUGH RMV 95-21	PR

General Comment:

COGCC Inspection Report Summary
 On 05/02/2023 at approximately 10:28 hours, I, Compliance Specialist, Wayne Smelser
 Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC CLOUGH RMV 95-21 pad.
 Location # 324053 in Garfield County Colorado.
 Please refer to Inspection 708900161 conducted on 03/24/2023, previous corrective action has been addressed.
 Location is in close proximity to High Priority/NSO/Density habitat areas.
 While there, I observed normal production operations.

During this inspection the following compliance issue was observed:

1. Stormwater - Stockpiled soils/insufficient BMP's, Soils/sediment choking off vegetation with a CA date of 05/19/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

Remote location - Wellhead only, production equipment for this well located at the RMV 96-28 Pad/Production Facility Location # 335122

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Pressure transducer & Taylor plug located on bradenhead, bradenhead valve is accessible		
Corrective Action:			Date:
Type: Deadman # & Marked	# 2		
Comment:	Marked		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			

Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 211586 Type: WELL API Number: 045-07347 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				Sparse to no gravel
		Ditches				
		Check Dams				
Check Dams						
		Compaction				
		Other	Fail			Stockpiled soils/insufficient BMP's
		Sediment Traps				
		Rip Rap				
Gravel						Sparse
Compaction						
Ditches						

Comment: Work has been done to address previous Stormwater corrective action, however there are now stockpiled soils near the sediment trap & no BMP's. Stockpiled soils/sediment is now choking off vegetation.

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation.

Date: 05/19/2023

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to Stormwater for observed compliance issue.	smelserw	05/04/2023
Remote location - Wellhead only, production equipment for this well located at the RMV 96-28 Pad/Production Facility Location # 335122		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708900397	Inspection 708900396 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6104492