

Inspection Photos

May 2, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335539

Location Name: McPherson A Pad

Inspection Document #: 702801490

Garfield County, CO

NENW Section 16 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: McPherson A Pad
Location ID: 335539



Photo 1. Photo taken from the entrance shows an overview of the location.



Inspection Photos
Location Name: McPherson A Pad
Location ID: 335539



Photo 2. Photos show production areas. Note debris at the tank battery (arrow).



Inspection Photos
Location Name: McPherson A Pad
Location ID: 335539




Photo 3. Photos show the tank secondary containment has been damaged (left) and an unmarked anchor (right).

Inspection Photos
Location Name: McPherson A Pad
Location ID: 335539




Photo 4. Photos show staining within the tank secondary containment.

Inspection Photos
Location Name: McPherson A Pad
Location ID: 335539



Photo 5. Photo shows staining at a pigging station to the northwest of the location.



Inspection Photos
Location Name: McPherson A Pad
Location ID: 335539



Photo 6. Photos show a berm to the west is unstabilized.



Inspection Photos
Location Name: McPherson A Pad
Location ID: 335539



Photo 7. Photos show a berm to the west is unstabilized.



Inspection Photos
Location Name: McPherson A Pad
Location ID: 335539



Photo 8. Photos show a berm to the west is unstabilized. Stormwater is traveling through the berm from the east (left) to the west (right).



Inspection Photos
Location Name: McPherson A Pad
Location ID: 335539



Photo 9. Photos taken to the northwest show stormwater is bypassing BMPs. Erosion degradation is evident.



Inspection Photos
Location Name: McPherson A Pad
Location ID: 335539



Photo 10. Photos taken to the northwest show stormwater is bypassing BMPs. Erosion degradation is evident.



Inspection Photos
Location Name: McPherson A Pad
Location ID: 335539



Photo 11. Photos taken to the northwest show BMPs not properly installed.



Inspection Photos
Location Name: McPherson A Pad
Location ID: 335539



Photo 12. Photos taken to the northwest show erosion degradation migrating offsite downslope of BMPs and the unstabilized location.

Inspection Photos
Location Name: McPherson A Pad
Location ID: 335539




Photo 13. Photos taken to the northwest show where stormwater from the access road ditch is cutting through a berm (left) and exiting to the west (right).



Inspection Photos
Location Name: McPherson A Pad
Location ID: 335539



Photo 14. Photos show an overview of stormwater BMPs in the northern interim area of the location. Note lack of stabilizing perennial vegetation and sediment migration.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801490

Inspection Photos
Location Name: McPherson A Pad
Location ID: 335539



Photo 15. Photos show erosion degradation at stormwater BMPs in the northern interim area of the location.

Inspection Photos
Location Name: McPherson A Pad
Location ID: 335539



Photo 16. Photos show erosion degradation at stormwater BMPs in the northern interim area of the location. Stormwater is eroding the sediment trap at the inlet, (left) base and walls/outlet (right).

Inspection Photos
Location Name: McPherson A Pad
Location ID: 335539



Photo 17. Photos show BMPs in the northern interim area of the location are not in proper functioning condition. Stormwater is bypassing the sediment trap outlet causing degradation.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801490

Inspection Photos
Location Name: McPherson A Pad
Location ID: 335539



Photo 18. Photos show erosion and sediment transport in the northern interim area of the location (left) migrating offsite and causing degradation to the adjacent pasture (right).

Inspection Photos
Location Name: McPherson A Pad
Location ID: 335539



Photo 19. Photo shows a slope to the south stabilized by perennial grasses.



Inspection Photos
Location Name: McPherson A Pad
Location ID: 335539



Photo 20. Photos show an example of interim areas to the south (left) and north (right).

