

# Inspection Photos

API: 009-06047

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 5/3/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 009-06047 | Date: 5/3/2023

## Inspection Photos



**Photo 1.** Facing toward the wellsite. The well sign does not comply with 605. Incorrect Operator Emergency number and missing information.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06047 | Date: 5/3/2023

## Inspection Photos



**Photo 2.** Facing southeast at the location. This area is bare of vegetation which maybe impacted soils from a historic spill.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06047 | Date: 5/3/2023



## Inspection Photos



**Photo 3.** Facing toward the pumpjack. The H2S sign is laying on the ground.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06047 | Date: 5/3/2023

## Inspection Photos



**Photo 4.** Facing toward the open top tank which still does not have secondary containment. The fence around the tank has fallen over in disrepair.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06047 | Date: 5/3/2023



## Inspection Photos



**Photo 5.** This area near the tank at northeast side of the location is bare of vegetation and has a white crusted soil which maybe impacted soils from a historic spill.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06047 | Date: 5/3/2023