

Inspection Photos

API: 009-06176

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 5/3/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06176 | Date: 5/3/2023

Inspection Photos



Photo 1. Facing toward the wellsite. There is no well sign posted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06176 | Date: 5/3/2023

Inspection Photos



Photo 2. Facing toward the open top tank which still does not have secondary containment and does not have signage.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06176 | Date: 5/3/2023

Inspection Photos



Photo 3. Facing toward the well head which appears inoperable. The base of the pumpjack has eroded and there are boards and debris around wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06176 | Date: 5/3/2023

Inspection Photos



Photo 4. There is a rusted out pipe that needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06176 | Date: 5/3/2023

Inspection Photos



Photo 5. Facing northeast toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06176 | Date: 5/3/2023