

Inspection Photos

API: 009-05101

Operator: CHACO ENERGY COMPANY

Inspection Date: 5/3/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos



Photo 1. The meter run still remains at the location. All equipment should have been removed within 3 months of abandonment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-05101 | Date: 5/3/2023

Inspection Photos



Photo 2. Facing north at the location which does not appear to have been reclaimed. Soils are bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-05101 | Date: 5/3/2023

Inspection Photos



Photo 3. Facing south at the location. Soils are bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-05101 | Date: 5/3/2023

Inspection Photos



Photo 4. There is metal t-post and wire debris that needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-05101 | Date: 5/3/2023