

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/04/2023

Submitted Date:

05/04/2023

Document Number:

707800324

**FIELD INSPECTION FORM**

Loc ID: 334642 Inspector Name: Ramsey, Scott On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
 10 Number of Comments  
 1 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 OGCC Operator Number: 10456  
 Name of Operator: CAERUS PICEANCE LLC  
 Address: 1001 17TH STREET #1600  
 City: DENVER State: CO Zip: 80202

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271436	WELL	PR	07/27/2006	GW	045-09884	PARADISE 11-8B (B11BW)	PR
271438	WELL	PR	06/17/2006	GW	045-09882	PARADISE 11-2B (B11BW)	PR
271440	WELL	SI	07/01/2022	GW	045-09881	PARADISE 11-1B (B11BW)	SI
272962	WELL	PR	06/12/2006	GW	045-10198	PARADISE 11-2C (B11BW)	PR
274452	WELL	PR	05/19/2006	GW	045-13349	PARADISE 11-7A (B11BW)	PR
274453	WELL	PR	06/16/2006	GW	045-13350	PARADISE 11-3A (B11BW)	PR

**General Comment:**

COGCC Inspection Report Summary  
 On Tuesday 5/2/2023, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus B11BW, at Location # 334642 in Garfield county Colorado.  
 Any Corrective Actions from previous Inspections that have not been addressed are still applicable.  
 While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:  
 1. Some areas of location show signs of lack of stabilization/compaction. Tracking control BMPs to minimize/mitigate tracking and offsite sediment transport are missing or insufficient.  
 Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:

Corrective Action:

Date:

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Type: Gas Meter Run	# 7		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

Type: Plunger Lift	# 6		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 6		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: <u>271436</u>	Type: <u>WELL</u>	API Number: <u>045-09884</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment: <u>Producing</u>				
Corrective Action:				Date:
Facility ID: <u>271438</u>	Type: <u>WELL</u>	API Number: <u>045-09882</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment: <u>Producing</u>				
Corrective Action:				Date:
Facility ID: <u>271440</u>	Type: <u>WELL</u>	API Number: <u>045-09881</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: _____				
Comment: <u>Last produced 7/2022</u>				
Corrective Action:				Date: _____
Facility ID: <u>272962</u>	Type: <u>WELL</u>	API Number: <u>045-10198</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment: <u>Producing</u>				
Corrective Action:				Date:
Facility ID: <u>274452</u>	Type: <u>WELL</u>	API Number: <u>045-13349</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment: <u>Producing</u>				
Corrective Action:				Date:
Facility ID: <u>274453</u>	Type: <u>WELL</u>	API Number: <u>045-13350</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment: <u>Producing</u>				
Corrective Action:				Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Ditches				
Compaction	Fail					
Ditches						
		Culverts				

Comment: 1. Some areas of location show signs of lack of stabilization/compaction. Tracking control BMPs to minimize/mitigate tracking and offsite sediment transport are missing or insufficient.

Corrective Action: Install or repair required BMPs

Date: 06/22/2023

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707800334	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6105689">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6105689</a>