

Inspection Photos
Location Name: CAERUS PICEANCE LLC COUEY J8E Pad
Location ID: 334821



Photo # 7036 From entrance to location



Photo # 7037 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC COUEY J8E Pad
Location ID: 334821



Photo # 7038 Location



Photo # 7039 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC COUEY J8E Pad
Location ID: 334821



Photo # 7040 Location



Photo # 7043 Flow line heating insulation open ended/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY J8E Pad

Location ID: 334821



Photo # 7132 Culvert needs maintenance (Culvert is located at the start of the access road right before the gates)