

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/05/2023

Submitted Date:

05/05/2023

Document Number:

708900409

FIELD INSPECTION FORM

Loc ID: 334821 Inspector Name: Smelser, Wayne On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 20 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus		COGCC.inspections@caerusoilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211052	WELL	PR	06/15/2002	GW	045-06810	COUEY T8-42	PR
261758	WELL	PR	08/07/2002	GW	045-07975	COUEY 8-10B	PR
261759	WELL	PR	05/16/2002	GW	045-07976	COUEY 8-10A	PR

General Comment:

[COGCC Inspection Report Summary](#)
On 05/05/2023 at approximately 10:53 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at CAERUS PICEANCE LLC COUEY J8E pad. Location # 334821 in Garfield County Colorado. Location is within High Priority/Density/Black Bear Habitat areas & within close proximity to NSO Habitat area. While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Stormwater - Culvert needs maintenance with a CA date of 05/20/2023
2. Flow line heating insulation open ended with a CA date of 05/12/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Any corrective actions not addressed from previous inspections are still applicable.

Location

Lease Road:			
	Type Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
	Type BATTERY		
Comment:			
Corrective Action:			Date:
	Type OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
	Type TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
	Type WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
	Comment: 911/970-285-2615		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Fencing/:			
	Type WELLHEAD		
Comment:	Cattle panels		
Corrective Action:			Date:
	Type OTHER		
Comment:	Pig launcher - cattle panels		
Corrective Action:			Date:
	Type SEPARATOR		
Comment:	Cattle panels		
Corrective Action:			Date:

Equipment:			corrective date
Type: Plunger Lift	# 3		
Comment:	All wells on plunger lift		
Corrective Action:			Date:
Type: Bradenhead	# 3		
Comment:	Pressure transducers located on all bradenhead. All bradenhead valves are accessible.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Flow line heating insulation open ended		
Corrective Action:	Operators will prevent & minimize adverse impacts to wildlife resources.		Date: 05/12/2023
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Summit meter house		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLs	STEEL AST		
Comment:	Centralized containment				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	12 bbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		
Comment:	Centralized containment				
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient		
Comment:					Date:
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					Date:
Corrective Action:					Date:
Flaring:					
Type					
Comment:					Date:
Corrective Action:					Date:

Inspected Facilities			
Facility ID: <u>211052</u>	Type: <u>WELL</u>	API Number: <u>045-06810</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<u>Producing Well</u>			
Comment:	<u>Producing, well on plunger lift</u>		
Corrective Action:		Date:	
Facility ID: <u>261758</u>	Type: <u>WELL</u>	API Number: <u>045-07975</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<u>Producing Well</u>			
Comment:	<u>Producing, well on plunger lift</u>		
Corrective Action:		Date:	
Facility ID: <u>261759</u>	Type: <u>WELL</u>	API Number: <u>045-07976</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<u>Producing Well</u>			
Comment:	<u>Producing, well on plunger lift</u>		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Compaction				
Compaction						
Ditches						
		Gravel				Sparse
		Culverts	Fail			Culvert needs maintenance
Gravel						Sparse

Comment: [Culvert at start of access road needs maintenance.](#)

Corrective Action: **Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation.**

Date: 05/20/2023

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to Equipment & Stormwater for observed compliance issues.	smelserw	05/05/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708900410	Inspection 708900409 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6106134