



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

corrective date

Type: Prime Mover

# 1

Comment: electric motor

Corrective Action:

Date:

Type: Bradenhead

# 1

Comment: plumbed to surface

Corrective Action:

Date:

Type: Ancillary equipment

# 1

Comment: electric

Corrective Action:

Date:

Type: Pump Jack

# 1

Comment:

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 239809 Type: WELL API Number: 123-07597 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 06/27/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment

User

Date

This inspection does not nullify any orders or NOAV from the COGCC.  
At time of inspection weather conditions were warm, overcast, calm.

medinaj

05/02/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699504645	inspection pictures	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6106405">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6106405</a>