

Lee, Austin

Subject:

FW: Pile between #1/#2

Attachments:

20230502_094154.jpg; 20230502_094206.jpg





Austin Lee, CPESC

STORMWATER & RECLAMATION ADVISOR – HSE ROCKIES



Zero In™ at oxy.com

From: Stormo, Drew (Energy Inspection Services LLC (EIS)) <Drew_Stormo@oxy.com>

Sent: Tuesday, May 2, 2023 2:43 PM

To: Lee, Austin <Austin_Lee@oxy.com>

Subject: FW: Pile between #1/#2

Drew Stormo

From: Eric Phillips <ephillips@toddcreekgolfclub.com>
Sent: Tuesday, May 2, 2023 2:22 PM
To: Stormo, Drew (Energy Inspection Services LLC (EIS)) <Drew_Stormo@oxy.com>
Subject: [EXTERNAL] Pile between #1/#2

WARNING - This message is from an EXTERNAL SENDER - be CAUTIOUS, particularly with links and attachments.

Drew,

Attached are the pictures of the soil pile that is in question. The pile consists of aeration plugs and sand from over the years. The pile was made by the golf course, not the crew that worked on the well.

Let me know if you have any other questions.

Thanks,

Eric Phillips

Golf Course Superintendent
Todd Creek Golf Club
ephillips@toddcreekgolfclub.com
14905 Xenia Street, Thornton, CO 80602



Sent from my Verizon, Samsung Galaxy smartphone
Get [Outlook for Android](#)