

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MV 53-28 /Frac Pad

Location ID: 335327



Photo #9867 From entrance to location.



Photo #9868 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MV 53-28 /Frac Pad

Location ID: 335327



Network time is not synchronized  
Local: May 3, 2023 at 1:03:40 PM MD  
N 39° 29' 55", W 108° 7' 18"



Network time is not synchronized  
Local: May 3, 2023 at 1:04:39 PM MD  
N 39° 29' 56", W 108° 7' 17"

Photo #9870 Calibration cards not conspicuously posted.

Photo #9872 Loadline open ended.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MV 53-28 /Frac Pad

Location ID: 335327



Photo #9873 Loadline open ended.



Photo #9874 Unused equipment.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MV 53-28 /Frac Pad

Location ID: 335327



**Photo #9875 Unused equipment.**