

Interim Reclamation and Stormwater Inspection

Date: 05/03/2023

Operator: FUNDARE RESOURCES OPERATING
COMPANY LLC - 10773

Location ID: 430314

Inspection Document #: 708200219

Weld County, CO

NESW Section 30 T10N R58W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Razor 30K Pad
Location ID: 430314



Photo 1. Southern portion of the production area. Photo illustrates that the cut slopes do not appear to be properly stabilized with non-uniform vegetation cover and evidence of sediment deposition into the production area. No apparent stormwater BMPs were observed to be implemented in these unstabilized areas.

Inspection Photos
Location Name: Razor 30K Pad
Location ID: 430314



Photo 2. See comments in Photo 1.

Inspection Photos
Location Name: Razor 30K Pad
Location ID: 430314



Photo 3. Facing east from the southwestern corner of the location; see comments in Photo 1.

Inspection Photos
Location Name: Razor 30K Pad
Location ID: 430314



Photo 4. Western portion of the location; see comments in Photo 1.

Inspection Photos
Location Name: Razor 30K Pad
Location ID: 430314



Photo 5. Rill erosion occurring on the unstabilized cut bank. Other than a perimeter stormwater ditch, no other stormwater BMPs were observed in this area.

Inspection Photos
Location Name: Razor 30K Pad
Location ID: 430314




Photo 6. See comments in Photo 5.

Inspection Photos
Location Name: Razor 30K Pad
Location ID: 430314



Photo 7. Overview of cut bank on west side of location; see comments in Photo 1.

Inspection Photos
Location Name: Razor 30K Pad
Location ID: 430314



Photo 8. Northwestern corner of the location/production area; see comments in Photo 1.

Inspection Photos
Location Name: Razor 30K Pad
Location ID: 430314



Photo 9. Facing west from the northern interim area. Photo illustrates that the interim areas require additional reclamation activities to meet Rule 1003 standards. Non-uniform vegetative cover resulting in areas of bare soil observed.

Inspection Photos
Location Name: Razor 30K Pad
Location ID: 430314



Photo 10. Facing east from the northern interim area; see comments in Photo 9.

Inspection Photos
Location Name: Razor 30K Pad
Location ID: 430314



Photo 11. Facing north from the eastern portion of the interim area. See comments in Photo 9.