

Inspection Photos

API: 071-07604

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 5/8/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos



Photo 1. Facing east toward the access road stream crossing. The old cement culverts still remain and need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07604 | Date: 5/8/2023

Inspection Photos



Photo 2. Facing southeast along the access road. This culvert along the access road has filled back in with sediment and needs to be cleaned out.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07604 | Date: 5/8/2023

Inspection Photos



Photo 3. There is erosion is occurring around the rock check dams which has not been repaired since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07604 | Date: 5/8/2023

Inspection Photos



Photo 4. There is erosion is occurring around the rock check dams which has not been repaired since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07604 | Date: 5/8/2023

Inspection Photos



Photo 5. Facing south toward the well site.

