

# Inspection Photos

API: 009-06495

Operator: OXY USA INC

Inspection Date: 5/3/2023



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06495 | Date: 5/3/2023

## Inspection Photos



**Photo 1.** Aerial imagery shows wellsite was bare of crop growth.



## Inspection Photos



**Photo 2.** Facing north toward the location. The location does not have any stubble from previous years crop.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06495 | Date: 5/3/2023

## Inspection Photos



**Photo 3.** Facing east toward the location. The location does not have any stubble from previous years crop.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06495 | Date: 5/3/2023

## Inspection Photos



**Photo 4.** Facing south toward the location. The location does not have any stubble from previous years crop.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06495 | Date: 5/3/2023

## Inspection Photos



**Photo 5.** Facing east toward the undisturbed reference area which has uniform crop stubble from previous year..



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06495 | Date: 5/3/2023