

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 217-21 pad

Location ID: 335213



Photo # 7234 From entrance to location



Photo # 7235 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 217-21 pad

Location ID: 335213



Photo # 7236 Location



Photo # 7237 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 217-21 pad

Location ID: 335213



Photo # 4959 From Inspection 708900261 conducted on 04/11/2023 Meter calibration info not conspicuously posted

Photo # 7241 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 217-21 pad

Location ID: 335213



Photo # 4960 From Inspection 708900261 conducted on 04/11/2023 Meter calibration info not conspicuously posted



Photo # 7243 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 217-21 pad

Location ID: 335213



Photo # 4958 From Inspection 708900261 conducted on 04/11/2023 Containment liner needs maintenance

Photo # 7247 Containment liner needs maintenance