

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/08/2023

Submitted Date:

05/09/2023

Document Number:

696204915

**FIELD INSPECTION FORM**Loc ID 322403 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 51130

Name of Operator: LOCIN OIL CORPORATION

Address: 600 TRAVIS ST STE 6161

City: HOUSTON State: TX Zip: 77002

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

3 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		dbenedict@locin.energy	
		ttaylor@locin.energy	
		hsirvent@locinoil.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210416	WELL	SI	06/01/2020	GW	045-06172	FEDERAL 1-34	RI
322403	LOCATION	AC			-	FEDERAL-67S104W 34NWNE	RI

**General Comment:**

On 5/8/2023, Reclamation Specialist Trujillo Reclamation Specialist Trujillo inspected Locin Oil Corporation's FEDERAL #1-34 Location in Garfield County, Colorado.

This is also a follow-up inspection to #696204808, to document compliance for the following corrective actions:

- Anchors not marked per Rule 1003.a
- Secondary containment BMP inadequate
- Stormwater-Labeling
- Good Housekeeping

It was observed that the Location remains out of compliance with COGCC Rules and Corrective Actions

Refer to the "Location" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Previous inspection observed that signage/labeling information was not posted, or information incorrect at a container stored adjacent to the well. Inspection required Operator to comply with 605.h.  Container has been removed from the Location. Corrective action is no longer applicable.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Previous inspection observed that signage/labeling information was not posted, or information incorrect at the 100 bbl condensate/produced water tank on the Location. Inspection required Operator to comply with 605.h.  It was observed in this inspection that the tank remains out of compliance with Rule 605.h.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	05/03/2023

Emergency Contact Number:

Comment: 970-858-7546/911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Pipe equipment observed improperly stored on Location has been removed.		
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Hog Paneling		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog Paneling		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	1	100 BBLS	STEEL AST		,	
Comment:		See "Signs/Marker" above regarding label requirements.				
Corrective Action:					Date:	

**Paint**

Condition					
Other (Content)	Condensate/Produced Water mix				
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:		Containment BMP appears to be in proper functioning condition at time of inspection.			
Corrective Action:					Date:

**Venting:**

Yes/No					
Comment:					
Corrective Action:				Date:	

**Flaring:**

Type				
Comment:				
Corrective Action:			Date:	

**Inspected Facilities**Facility ID: 210416 Type: WELL API Number: 045-06172 Status: SI Insp. Status: RI**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Records show well status "Shut In" since June 2020.

Operator submitted Form 5B #403291551 to designate well as "Inactive" per Rule 434.c. (1)B.

Operator received approval of "Alternative MIT" (Form 4 #403062371) with conditions that " At least once a year shut in bradenhead for 7 days or until the pressure reaches the bradenhead threshold and perform a bradenhead test. Report results on a Form 17, as specified in Rule 420 or other Director approved submittal method".

Date of last bradenhead test 5/25/2022. Per COAs, subsequent bradenhead testing/reporting required by 5/25/2023.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 322403 Type: LOCATION API Number: - Status: AC Insp. Status: RI

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? Fail

Comment

Inspection #693805277 and #696204808 observed anchors lacked marking per Rule 1003.a. Inspection required Operator to "Install proper guy line markers per Rule 1003.a by 11/30/2022.

It was observed in this inspection that anchors on the NW/NE/SE ends of the Location remain improperly marked per 1003.a requirements.

This CA has not been addressed and remains applicable.

Corrective Action

Comply with 1003.a

Date **11/30/2022**

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Inspection #696204808 observed gully erosion forming across the access road due to runoff. Inspection also observed that the containment BMP at the methanol tank has filled with fluid, and is no longer adequate to contain a spill. Inspection required Operator to comply with Rule 1002.f.

It was observed in this inspection that the methanol tank/BMP have been removed.

It was also observed that BMPs to manage runoff in a manner that minimizes erosion, degradation and sediment transport at the access road remain missing or insufficient; regrading alone to repair gully erosion will not be sufficient. Corrective action has not been addressed and remains applicable.

Corrective Action: **Comply with 1002.f: Install or repair required stormwater and erosion control BMPs at access road to properly manage runoff.**

Date: 04/07/2023

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	119488	400989225	
	119488	400989225	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696204916	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6109139">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6109139</a>