

Inspection Photos
Location Name: Pace-Connelly #2
Location ID: 318512



Photo 1 WH sign.

Photo 2 Stained soil by the WH.

Inspection Photos
Location Name: Pace-Connelly #2
Location ID: 318512



Photo 3 pump jack.

Photo 4 TB sign.

Inspection Photos
Location Name: Pace-Connelly #2
Location ID: 318512



Photo 5 TB.

Photo 6 Horizontal Heated Separator and Flow line manifold house.

Inspection Photos
Location Name: Pace-Connelly #2
Location ID: 318512



Photo 7 Stained soil under flow line manifold.

Photo 8 ECD.

Inspection Photos
Location Name: Pace-Connelly #2
Location ID: 318512



Photo 9 Compressor house.

Photo 10 Stained soil under skid in compressor house.

Inspection Photos
Location Name: Pace-Connelly #2
Location ID: 318512



Photo 11 Electric panel at Compressor house is on.

Photo 12 Vertical Separator.

Inspection Photos
Location Name: Pace-Connelly #2
Location ID: 318512



Photo 13 Gas Meter Run LOTO.

Photo 14 Gas Meter Run.

Inspection Photos
Location Name: Pace-Connelly #2
Location ID: 318512



Photo 15 Anadarko Gas Meter inventory # 295482.

Photo 16 Gas Meter Run shows yesterdays flow at 3.579175 and a monthly flow at 39.91647 .