

# Inspection Photos

May 8, 2023

Operator: Beeman Oil & Gas Inc- #7125

Location ID: 433308

Location Name: Bulldog /17-11H-893

Inspection Document #: 702801506

Moffat County, CO

NWNW Section 17 T8N R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Bulldog /17-11H-893  
Location ID: 433308



**Photo 1.** Photo taken from the Location entrance shows an overview of the eastern portion of the Location.



**Photo 2.** Photo taken from the Location entrance shows an overview of the western portion of the Location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801506

Inspection Photos  
Location Name: Bulldog /17-11H-893  
Location ID: 433308



**Photo 3.** Photo shows an overview of the unstabilized cut slope at the east of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission


Department of Natural Resources

Inspection Number: 702801506

Inspection Photos  
Location Name: Bulldog /17-11H-893  
Location ID: 433308



**Photo 4.** Photo taken from the south of the Location shows gully erosion occurring on unstabilized slopes.



**Photo 5.** Photo shows gully erosion on the cut slope to the east.

Inspection Photos  
Location Name: Bulldog /17-11H-893  
Location ID: 433308



**Photo 6.** Photos show rill erosion on the unstabilized cut slope.



Inspection Photos  
Location Name: Bulldog /17-11H-893  
Location ID: 433308



**Photo 7.** Photo shows rill erosion on the unstabilized cut slope to the northeast.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801506

Inspection Photos  
Location Name: Bulldog /17-11H-893  
Location ID: 433308



**Photo 8.** Photo shows rill erosion on the unstabilized cut slope to the northeast.



Inspection Photos  
Location Name: Bulldog /17-11H-893  
Location ID: 433308



**Photo 9.** Photos show a methanol tank at the north of the Location lacks wildlife protection BMPs on the secondary containment stock tank. Photos also shows impacted fluid within secondary containment.

Inspection Photos  
Location Name: Bulldog /17-11H-893  
Location ID: 433308



**Photo 10.** Photo taken to the north shows inadequate wildlife protection BMPs on the secondary containment stock tank.



**Photo 11.** Photo taken to the north shows trash (aerosol can).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801506

Inspection Photos  
Location Name: Bulldog /17-11H-893  
Location ID: 433308



**Photo 12.** Photos show trash.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801506

Inspection Photos  
Location Name: Bulldog /17-11H-893  
Location ID: 433308



**Photo 13.** Photos show staining below a crude oil tank, which appears to be leaking.

Inspection Photos  
Location Name: Bulldog /17-11H-893  
Location ID: 433308




Photo 14. Photos show two (2) unmarked anchors.

Inspection Photos  
Location Name: Bulldog /17-11H-893  
Location ID: 433308



Photo 15. Photos show production areas.



Inspection Photos  
Location Name: Bulldog /17-11H-893  
Location ID: 433308



Photo 16. Photos show production areas.

