

**KT Resources LLC
Ant Hill Unit 18-43
Location #316341**



Access road at location



Entrance to location

**KT Resources LLC
Ant Hill Unit 18-43
Location #316341**



Tank battery signs



Stained soil behind produced water tank

**KT Resources LLC
Ant Hill Unit 18-43
Location #316341**



Oil leak on crude oil tank



Soil staining from leak on crude oil tank

**KT Resources LLC
Ant Hill Unit 18-43
Location #316341**



No visible display of gas meter calibration



Erosion and sediment along access road at location

**KT Resources LLC
Ant Hill Unit 18-43
Location #316341**



Bare slope and sediment migration off location



Diversion ditch full of sediment

**KT Resources LLC
Ant Hill Unit 18-43
Location #316341**



Diversion ditch damage and full of sediment



Erosion and sediment off location

**KT Resources LLC
Ant Hill Unit 18-43
Location #316341**



Sediment migration leaving location



Road erosion. Sediment migration off location

**KT Resources LLC
Ant Hill Unit 18-43
Location #316341**



Location view from Southeast corner



Location view from Southwest corner

**KT Resources LLC
Ant Hill Unit 18-43
Location #316341**



Location view from Northwest corner



Location view from Northeast corner

