

**KT Resources LLC  
Ant Hill Unit 18-42  
Location #316308**



**Access road at location entrance**



**Entrance to location**



**KT Resources LLC  
Ant Hill Unit 18-42  
Location #316308**




**Alternate entrance to location**



**Signs at tank battery**



KT Resources LLC  
Ant Hill Unit 18-42  
Location #316308



Debris



Debris



**KT Resources LLC  
Ant Hill Unit 18-42  
Location #316308**



**Inadequate wildlife protection**



**Inadequate wildlife protection**





**KT Resources LLC  
Ant Hill Unit 18-42  
Location #316308**



**Gas meter calibration card not visibly displayed**



**Erosion and sediment migration from alternate entrance to location**



**KT Resources LLC  
Ant Hill Unit 18-42  
Location #316308**



**Sediment migration from location**



**Sediment migration from location**



**KT Resources LLC  
Ant Hill Unit 18-42  
Location #316308**



**Location view from Northeast corner**



**Location view from Northwest corner**



**KT Resources LLC  
Ant Hill Unit 18-42  
Location #316308**



**Location view from Southwest corner**



**Location view from Southeast corner**