

# Inspection Photos

May 8, 2023

Operator: Beeman Oil & Gas Inc- #7125

Location ID: 429116

Location Name: Bulldog /20-12H-892

Inspection Document #: 702801512

Moffat County, CO

SWNW Section 20 T8N R92W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Bulldog /20-12H-892  
Location ID: 429116



**Photo 1.** Photo taken from the northeast shows an overview of the northern portion of the Location. Photo also shows dense cover of cheatgrass (List C Noxious) and Russian thistle (undesirable plant species).



**Photo 2.** Photo taken from the northeast shows an overview of the southern portion of the Location. Refer to additional Photo 1 comments.



Inspection Photos  
Location Name: Bulldog /20-12H-892  
Location ID: 429116



**Photo 3.** Photo taken from the south shows an overview of the location. Note the eroding cut slope (arrow).

Inspection Photos  
Location Name: Bulldog /20-12H-892  
Location ID: 429116



**Photo 4.** Photos show a examples of Scotch thistle (left) and bull thistle (right), CO List B Noxious Weeds which are widespread on Location.

Inspection Photos  
Location Name: Bulldog /20-12H-892  
Location ID: 429116



**Photo 5.** Photo shows bull and Scotch thistle and dense coverage of emerging Russian thistle and cheatgrass.



**Photo 6.** Photo taken at the stock pond to the east of the Location shows an example of Scotch thistle, a CO List B Noxious Weed on Location. Note also extensive native rangeland in the background which is free of noxious weeds. Thistle on location is acting as a weed source in habitat otherwise free of list B noxious weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801512

Inspection Photos  
Location Name: Bulldog /20-12H-892  
Location ID: 429116



**Photo 7.** Photo taken from the east of the Location shows a drain pipe which leads through the fill slope. Stormwater is bypassing the drain and eroding the fill slope. Note also scotch and bull thistles.



**Photo 8.** Photo taken from the east of the location shows where stormwater is bypassing a drain pipe and eroding the fill slope. Note the slope is densely colonized by noxious weeds and undesirable plant species.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801512

Inspection Photos  
Location Name: Bulldog /20-12H-892  
Location ID: 429116



**Photo 9.** Photo taken from the fill slope at the southeast shows a fill slope drain. Stormwater is bypassing the drain and causing erosion. Photo left shows the inlet, right shows the outlet.



Inspection Photos  
Location Name: Bulldog /20-12H-892  
Location ID: 429116



**Photo 10.** Refer to Photo 9 comments. Note also noxious weeds and undesirable plant species.

Inspection Photos  
Location Name: Bulldog /20-12H-892  
Location ID: 429116



**Photo 11.** Photos taken at the northeast of the Location show rill erosion occurring on the unstabilized and unprotected cut slope. Photos also show Russian thistle, an undesirable plant species emerging.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801512

Inspection Photos  
Location Name: Bulldog /20-12H-892  
Location ID: 429116



**Photo 12.** Photo taken at the north of the Location shows rill erosion occurring on the unstabilized and unprotected cut slope.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801512

Inspection Photos  
Location Name: Bulldog /20-12H-892  
Location ID: 429116



**Photo 13.** Photos show the topsoil stockpile at the west of the location. Pile is colonized by noxious weeds and undesirable plant species. Desirable and or perennial vegetation establishment is sparse.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801512

Inspection Photos  
Location Name: Bulldog /20-12H-892  
Location ID: 429116



**Photo 14.** Photos show stained soils east of the tank battery (left) and unused hose equipment within the tank battery secondary containment berm (right).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801512

Inspection Photos  
Location Name: Bulldog /20-12H-892  
Location ID: 429116



**Photo 15.** Photos show production areas. The battery sign does not comply with Rule 605.e (left). The wellhead sign does not comply with Rule 605.d (right).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801512

Inspection Photos  
Location Name: Bulldog /20-12H-892  
Location ID: 429116



**Photo 16.** Photos show production areas to the north. Wildlife protection BMPs are missing/insufficient on the methanol tank secondary containment stock tank. The tank label is peeling and faded. Safety and identifying information is not legible.

Inspection Photos  
Location Name: Bulldog /20-12H-892  
Location ID: 429116



**Photo 17.** Photos show trash/debris.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801512

Inspection Photos  
Location Name: Bulldog /20-12H-892  
Location ID: 429116



**Photo 18.** Photos show trash/debris.

