

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/10/2023

Submitted Date:

05/12/2023

Document Number:

707800363

## FIELD INSPECTION FORM

 Loc ID: 324702  
 Inspector Name: Ramsey, Scott  
 On-Site Inspection:   
 2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**
 OGCC Operator Number: 34162  
 Name of Operator: GILS HOT OIL SERVICE  
 Address: P O BOX 418  
 City: STRASBURG State: CO Zip: 80136
**Findings:**

- 18 Number of Comments
- 9 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Paine, Gilbert	303-622-9751	cherokeeequipment@hotmail.com	owner/operator
, COGCC		dnr_cogccengineering@state.co.us	engineering

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212480	WELL	PR	05/01/2021	OW	057-06374	STATE 3-X	PR

**General Comment:**

## COGCC Inspection Report Summary

On Wednesday 5/10/2023, I, Inspector Scott Ramsey, conducted a routine inspection at Gils hot oil service State 3-X, at Location # 324702 in Jackson county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed well pump jack not operating at time of inspection. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area.

Previous Inspector has C/A's for stored equipment, lack of Braden head and stained soil from inspection # 689806733.

During this inspection the following compliance issues were observed:

1. No BMP's installed to prevent sediment migration from occurring on location.
2. Location and access is covered with vegetation.
3. Lease road shows signs of lack of stabilization/compaction.
4. Access road to well is not marked or maintained
5. No API posted on well head and partial emergency contact
6. Battery signage is lacking information
7. Secondary containment is insufficient.
8. No evidence of Braden Head access.
9. Valves on tanks missing cap/plug
10. Tank is open to atmosphere through hole on side of tank with hose pushed into. Strong hydrocarbon odor.
11. Stored equipment on location
12. Random debris
13. Staining at well head

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:	Battery signage is lacking information		
Corrective Action:	Provide proper signage as per the rule	Date:	06/23/2023
Type	WELLHEAD		
Comment:	Well head signage is lacking information		
Corrective Action:	Provide proper signage per the rule	Date:	06/23/2023

Emergency Contact Number:

Comment:

Corrective Action:

Date:

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Stored equipment on location		
Corrective Action:	Remove all stored equipment from location	Date:	06/23/2023
Type	OTHER		
Comment:	Staining at well head		
Corrective Action:	Remove stained material and dispose of properly	Date:	05/26/2023
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove all debris	Date:	05/26/2023
Type	OTHER		
Comment:	Valves on tanks missing cap/plug		
Corrective Action:	Install caps/plugs	Date:	05/26/2023

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Barbed wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbed wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Other	# 1		
Comment:	Oil well head		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 0		
Comment:	No evidence of Braden Head access.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection	Date:	05/22/2023

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	200 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				Inadequate
Comment:	Secondary containment is insufficient.			
Corrective Action:	Repair or install berms or other secondary containment devices			Date:
				06/23/2023

**Venting:**

Yes/No		
Comment:	Tank is open to atmosphere through hole on side of tank with hose pushed into. Strong hydrocarbon odor. Follow up inspection will be done with FLIR camera,	
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 212480 Type: WELL API Number: 057-06374 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing according to data base, valves open.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: 1.No evidence of any storm water controls to prevent sediment migration or tracking BMP's to prevent sediment from location being transported from location.  
2. Location and access is covered with vegetation.  
3. Lease road shows signs of lack of stabilization/compaction.  
4. Access road to well is not marked or maintained

Corrective Action: Install, maintain or repair required BMPs

Date: 06/23/2023

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707800369	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6113822">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6113822</a>