

Inspection Photos
Location Name: CAERUS PICEANCE LLC A17E Pad
Location ID: 334953



Photo # 7530 From entrance to location



Photo # 7531 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC A17E Pad
Location ID: 334953



Photo # 7532 Location



Photo # 7533 Location



Inspection Photos
Location Name: CAERUS PICEANCE LLC A17E Pad
Location ID: 334953



Photo # 7534 Location



Photo # 7536 Flowline heating insulation open ended

Inspection Photos
Location Name: CAERUS PICEANCE LLC A17E Pad
Location ID: 334953



Photo # 7537 Flowline heating insulation open ended



Photo # 7550 Unmarked deadman

