

Inspection Photos
Location Name: CAERUS PICEANCE LLC O29NE Pad
Location ID: 335085



Photo # 7639 From entrance to location



Photo # 7640 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC O29NE Pad
Location ID: 335085



Photo # 7641 Location



Photo # 7642 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC O29NE Pad
Location ID: 335085



Photo # 7644 Location



Photo # 7645 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC O29NE Pad
Location ID: 335085



Photo # 7647 Stained gravel inside secondary containment



Photo # 7649 Stained gravel inside secondary containment

Inspection Photos
Location Name: CAERUS PICEANCE LLC O29NE Pad
Location ID: 335085



Photo # 7650 Stained gravel inside secondary containment



Photo # 7652 Weeds in secondary containment

Inspection Photos
Location Name: CAERUS PICEANCE LLC O29NE Pad
Location ID: 335085



Photo # 7653 Weeds in secondary containment



Photo # 7654 Weeds in secondary containment

Inspection Photos
Location Name: CAERUS PICEANCE LLC O29NE Pad
Location ID: 335085



Photo # 7657 Flowline heating insulation open ended



Photo # 7660 Stained soils & gravel

Inspection Photos
Location Name: CAERUS PICEANCE LLC O29NE Pad
Location ID: 335085



Photo # 7661 Stained soils & gravel