

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

05/15/2023

Submitted Date:

05/15/2023

Document Number:

712700155

**FIELD INSPECTION FORM**
 Loc ID 312009 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10766

Name of Operator: ARKOMA OPERATIONS LLC

Address: 2121 S COLUMBIA AVE SUITE 101

City: TULSA State: OK Zip: 74114

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		SJBcompliance@arkomaops.com	All SW Inspections
Price, Andrew	(918) 260-8324	aprice@arkomaops.com	All SW Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281477	WELL	PR	05/29/2020	CBM	067-09089	IGE 108	PR
297341	WELL	PR	10/10/2014	CBM	067-09609	IGE 134	PR

**General Comment:**

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: [Present](#)

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	<a href="#">And wellhead, cattle panel.</a>		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	<a href="#">gas motor</a>		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		

Comment:	2-3" from separator to meterhouse. Calibrated within 1 year.			
Corrective Action:			Date:	
Type: Flow Line	# 2			
Comment:	2-3" from wellhead to separator.			
Corrective Action:			Date:	
Type: Gathering Line	# 1			
Comment:	Partially buried valve can.			
Corrective Action:			Date:	
Type: Ancillary equipment	# 2			
Comment:	Wellhead			
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		37.114490,-107.689900
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other				
Comment:	Plastic "Polystar" with plastic liner.			
Corrective Action:				Date:

**Wells Served By Facilities Above****AirsID**

API Number	API Number	AirsID
067-09609		

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 281477 Type: WELL API Number: 067-09089 Status: PR Insp. Status: PRFacility ID: 297341 Type: WELL API Number: 067-09609 Status: PR Insp. Status: PR**BradenHead**Date of Last Brhd Test: 10/26/2022 Annual Brhd Completed?           Last Brhd Test Results Initial Surf Csg Pressure: 75 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: Corrective Action: Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Pass					
Berms	Pass	Gravel	Pass			
Compaction	Pass	Culverts	Pass			

Comment: No visible erosion or sediment migration observed during inspection.  
Installed wattles need maintenance or removal. See Photo #2.

Corrective Action: Repair or remove required BMPs per Rule 1002.f.(2)C.

Date: 05/31/2023

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700161	Well Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6115084">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6115084</a>