

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/15/2023

Submitted Date:

05/15/2023

Document Number:

712700157

FIELD INSPECTION FORM

Loc ID 326543 Inspector Name: Pattillo, Curtis On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10679
Name of Operator: LOGOS OPERATING LLC
Address: 2010 AFTON PLACE
City: FARMINGTON State: NM Zip: 87401

Findings:

- 10 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|-------|----------------------------------|--------------------------|
| , General | | regulatory@logosresourcesllc.com | All SW field inspections |
| Fields, Vanessa | | vfields@logosresourcesllc.com | All SW Inspections |
| Labowskie, Steve | | steve.labowskie@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 256122 | WELL | PR | 02/01/2023 | GW | 067-08272 | IGNACIO 33-8 5A | PR |

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|----------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

| Type | | | corrective date |
|-----------------------------------|----------------------------------|-------|-----------------|
| Type: Ancillary equipment | # 2 | | |
| Comment: | Telemetry | | |
| Corrective Action: | | Date: | |
| Type: Gathering Line | # 1 | | |
| Comment: | Above g.round valve | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | wellhead | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Flow Line | # 1 | | |
| Comment: | 2-3" from wellhead to separator. | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 3 | | |
| Comment: | | | |

| | |
|--------------------|-------|
| Corrective Action: | Date: |
|--------------------|-------|

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------------|---|----------|-------|---------|-----------------------|
| PRODUCED WATER | 1 | 200 BBLs | OTHER | | 37.115180,-107.699240 |

Comment: Partially buried steel tank.

| | |
|--------------------|-------|
| Corrective Action: | Date: |
|--------------------|-------|

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |

Comment:

| | |
|--------------------|-------|
| Corrective Action: | Date: |
|--------------------|-------|

Venting:

| | | | | |
|--------------------|----|--|-------|--|
| Yes/No | NO | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 256122 Type: WELL API Number: 067-08272 Status: PR Insp. Status: PR

BradenHead

Date of Last Brhd Test: 05/03/2023 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms | Pass | | | | | |
| Compaction | Pass | Gravel | Pass | | | |

Comment: Location rutted, recent precipitation.
No visible erosion or sediment migration observed during inspection.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 712700163 | Well Location Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6115086 |