

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/09/2023

Submitted Date:

05/09/2023

Document Number:

708900435

FIELD INSPECTION FORMLoc ID 335213 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

23 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211589	WELL	PR	05/01/2000	GW	045-07350	CLOUGH RMV 217-21	PR
275898	WELL	PR	07/31/2005	GW	045-10400	CLOUGH RWF 513-21	PR
275899	WELL	PR	07/23/2005	GW	045-10401	CLOUGH RWF 413-21	PR
276274	WELL	PR	08/29/2005	GW	045-10433	CLOUGH RWF 423-21	PR
276320	WELL	PR	08/29/2005	GW	045-10443	CLOUGH RWF 422-21	PR

General Comment:**COGCC Inspection Report Summary**

On 05/09/2023 at approximately 09:25 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC CLOUGH RMV 217-21 pad.

Location # 335213 in Garfield County Colorado.

Please refer to Inspection 708900261 conducted on 04/11/2023, 2 of the 4 corrective actions have not been completed.

Location is within High Priority/Density habitat areas.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Containment liner needs maintenance with a CA date of 05/01/2023
2. Meter calibration info not conspicuously posted with a CA date of 04/21/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location

Lease Road:

	Type Access		
comment:			
Corrective ActionL		Date:	

Overall Good: ☐**Signs/Marker:**

	Type BATTERY		
Comment:			
Corrective Action:		Date:	
	Type WELLHEAD		
Comment:	Multiple wellhead signs weathered & cracking but still legible		
Corrective Action:		Date:	
	Type TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
	Type OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911/970-285-9377		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

	Type WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
	Type OTHER		
Comment:	Meter house - hog panels		
Corrective Action:		Date:	
	Type TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 5		
Comment:	Meter calibration info not conspicuously posted		
Corrective Action:	The Operator will conspicuously post and maintain the date of the last meter calibration in a legible condition at each meter at all times	Date:	04/21/2023
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 15		
Comment:	Marked		
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:	RMV 217-21 wellhead equipped with a Taylor plug on bradenhead. No form of pressure monitoring equipment located on the other 4 bradenheads, all bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Inadequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Containment liner needs maintenance			
Corrective Action:	The liner will be sufficiently impervious so that any discharge from a primary containment system will not escape containment before cleanup occurs.			Date: 05/01/2023

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--

Inspected Facilities									
Facility ID:	211589	Type:	WELL	API Number:	045-07350	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	275898	Type:	WELL	API Number:	045-10400	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	275899	Type:	WELL	API Number:	045-10401	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	276274	Type:	WELL	API Number:	045-10433	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	276320	Type:	WELL	API Number:	045-10443	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				Sparse
		Compaction				
Gravel						Sparse
Compaction						Light

Comment: Location appears to have some gravel throughout the location with light compaction. Places with sparse to no gravel are present on location. Sparse gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to Equipment & Tanks & Berms for observed compliance issues.	smelserw	05/09/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403398271	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6108882
403398315	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6108884
708900436	Inspection 708900435 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6108830