

Interim Reclamation and Stormwater Inspection

May 11, 2023

Operator: UPLAND EXPLORATION LLC- #10701

Location ID: 462919

Inspection Document #: 697504670

Weld County, CO

SESE Section 21 T11N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Little Lady 21/South Well Pad
Location ID: 462919



Photo 1. Drone aerial imagery illustrates the northern half of the location. Photo illustrates interim reclamation has been performed; however, interim reclamation is not complete due to the lack of soil stabilization on the topsoil stockpile (orange arrow) and throughout portions of the interim reclamation area.



Inspection Photos

Location Name: Little Lady 21/South Well Pad

Location ID: 462919



Photo 2. Drone aerial imagery illustrates the southern half of the location. See comments under Photo 1.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697504670

Inspection Photos
Location Name: Little Lady 21/South Well Pad
Location ID: 462919



Photo 3. Photo taken from the southern location, facing West. See comments under Photo 1.



Photo 4. Photo taken from the northwestern location, facing South. See comments under Photo 1.



Inspection Photos
Location Name: Little Lady 21/South Well Pad
Location ID: 462919



Photo 5. Photo taken from the southern interim reclamation area, facing East. Photo illustrates an area highlighted in red. This area is an example of COGCC's expectation of soil stabilization that shall be reflective throughout the interim reclamation areas, including the topsoil stockpile.



Inspection Photos
Location Name: Little Lady 21/South Well Pad
Location ID: 462919



Photo 6. Photo taken from the topsoil stockpile, facing East. Photo illustrates the topsoil stockpile which has been seeded; however, the topsoil stockpile lacks soil stabilization.



Photo 7. Photo taken from the facility location, facing West. Photo illustrates unused equipment (hose) has been removed from within secondary containment.



Inspection Photos
Location Name: Little Lady 21/South Well Pad
Location ID: 462919



Photo 8. Photo taken from the northeastern location, facing South. Photo illustrates the eastern perimeter has been mowed; however, weed growth was observed and weed debris has not been properly disposed of. Piles of weed debris were observed throughout the eastern perimeter.



Photo 9. Photo taken from the eastern perimeter of location. Photo illustrates Kochia seedling growth.

Inspection Photos
Location Name: Little Lady 21/South Well Pad
Location ID: 462919



Photo 10. Photo taken from the eastern perimeter of location. Photo illustrates a pile of Kochia weed debris (red arrow), which is a weed seed source, and trash (yellow arrows).



Photo 11. Photo taken from the entrance of location. Photo illustrates a pile of weed debris (red polygon) and trash (yellow arrows).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697504670